

~~SECRET~~

PRIORITY

OUT58396

multi

P 030119Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 7085.

1036 MAY 3 01 32Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

CAMERA B 7 WAS USED IN MISSION 8089 FLOWN ON 29 APRIL
1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

3 MAY 1966

B. 9R SIDE: THE TITLING ON FRAMES 1 AND 2 ARE SMEARED.
THERE IS A MANUFACTURING SPLICE AND AN ADJACENT FOGGED AREA IN
FRAME 420. THERE IS A HEAT SPLICE THROUGH FRAME 1267.

C. 9L SIDE: MINOR EDGE STATIC AND EDGE FOG OCCURS
INTERMITTENTLY THROUGHOUT THE MISSION. VERY MINOR ROLLER CHATTER
IS PRESENT ALONG THE INBOARD EDGE. A HEAT SPLICE WAS MADE
BETWEEN FRAMES 269/270 AND THROUGH FRAME 1252. A MANUFACTURING
SPLICE IS LOCATED BETWEEN FRAMES 1531/1532.

D. THE FRAME COUNTER SKIPPED NUMBER 002. THE LAST TITLED
FRAME IS 2556.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADE OR OBSCURED 40 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/

~~SECRET~~